

Raytec Vario2.5 Hybrid IPPoE Firmware

Release Notes

© Raytec Ltd 2025


Contents

1. RELEASE VERSION 3.7.2 (APRIL 2025)	3
1.1. NEW FEATURES	3
1.2. REMOVED FEATURES	4
1.3. FIXED ISSUES	4
1.4. KNOWN ISSUES.....	4
3. RELEASE VERSION 3.7.1 (JUNE 2023)	5
3.1. NEW FEATURES	5
3.2. REMOVED FEATURES	6
3.3. FIXED ISSUES.....	6
3.4. KNOWN ISSUES.....	6
4. RELEASE VERSION 3.6.0 (MARCH 2021)	7
4.1. NEW FEATURES	7
4.2. REMOVED FEATURES	7
4.3. FIXED ISSUES.....	7
4.4. KNOWN ISSUES.....	7
5. RELEASE VERSION 3.5.4 (AUGUST 2020)	8
5.1. NEW FEATURES	8
5.2. REMOVED FEATURES	8
5.3. FIXED ISSUES.....	8
5.4. KNOWN ISSUES.....	8

1. Release Version 3.7.2 (April 2025)

1.1. New Features

Anyone trying to sign in with the operator (user) account will be forced to change the default password if detected.



Var2-IP-hy6 / VARIO2IP Raytec Vario2 Hybrid IP Light Controller


User Log On

Enter the user name and password to access the lamp.

User name:	<input type="text"/>
Password:	<input type="password"/>

Log On

Copyright © Raytec



Var2-IP-hy6 / VARIO2IP Raytec Vario2 Hybrid IP Light Controller

User Log On

Default password detected, please change password for the account

Password:	<input type="password"/>
Confirm Password:	<input type="password"/>


Show Passwords

Change

Copyright © Raytec

1.2. Removed Features

Side menu is no longer visible in the login page if the admin/user is not signed in. This will be shown once they have signed in.



1.3. Fixed Issues

None

1.4. Known Issues

None


3. Release Version 3.7.1 (June 2023)

3.1. New Features

HTTPS

It is now possible to upload a certificate and private key to a lamp to enable encrypted communication using HTTPS.


The web interface now has a page Certificate Upload which looks as follows:



The user must upload a certificate file and private key, these files must be in .der format as this makes the files smaller and allows them to be uploaded and stored in a timely manner.

It is important that files uploaded use ECDSA 256-bit keys, the reason this has been chosen by Raytec is because we have a memory and power constrained device and by using ECDSA with 256-bit keys (over something like RSA with 2048 bit keys) is to give our users security whilst keeping the product working without any lags or issues, our processor doesn't have the capability to do RSA encryption/decryption in a timely manner.

After uploading the files, the lamp will restart and on typing https://<lamp_ip_address> into your browser you should see the lock indicating that the connection is secure:



Raytec Global (excluding Americas)

Tel: +44 (0) 01670 520055
 Fax: +44 (0)1670 819760
 sales@rayteccctv.com

Raytec Americas:

Tel: +1 613 270 9990
 Toll Free: +1 888 505 8335
 ussales@rayteccctv.com

www.rayteccctv.com

You can now navigate the web interface securely and by preceding your HTTP API commands with https:// you'll now be able to send these encrypted.

*To support this updated firmware, Raytec have released an update to their DiscoMan Software to simplify certificate creation and upload. In addition to this, there is also a **Raytec HTTPS Setup Guide** which can be found in this download package.*

3.2. Removed Features

None

3.3. Fixed Issues

None

3.4. Known Issues

None

4. Release Version 3.6.0 (March 2021)

4.1. New Features

None

4.2. Removed Features

None

4.3. Fixed Issues

Photocell Hysteresis

Photocell hysteresis has now been applied to all lamp modes and the off level has been adjusted to be 40 lux higher than the configured on level rather than the previous 60 lux irrespective of on level.

This fix has been made because the photocell on and off value was the same in VMS mode and this led to a lot of night and day events leading to incorrect behaviour in our integrations.

4.4. Known Issues

None

5. Release Version 3.5.4 (August 2020)

5.1. New Features

See separate Feature Update document **Vario2 IPPOE 2.5 – Feature Update g 05-10-20** (included in this release package)

5.2. Removed Features

None

5.3. Fixed Issues

None

5.4. Known Issues

None